



**COMPLIANT FUEL OIL NON-AVAILABILITY REPORT
NORTH AMERICAN EMISSION CONTROL AREA (NA-ECA)**

Name of vessel M.V. Zeyno		Flag Malta	IMO number 9700421
(If other relevant registration number is available, enter here)			
Provide a description of the vessel's voyage plan in place at the time of entry into the North American ECA (Attach copy of plan if available) Vessel will enter ECA in position 54 24 N 139 42 W on 20th October 2014. (Voyage Plan Attached)			
Last port of departure Yangzhou, China		Date of departure from last port (dd-mm-yyyy) 02-10-2014	
First port of arrival in Canada Prince Rupert		Date of arrival at first Canadian port (dd-mm-yyyy) 21-10-2014	
Date vessel first received notice that it would be transiting in the NA-ECA (dd-mm-yyyy) 01-10-2014			
Vessel's location at the time of notice Yangzhou, China			
Date/time vessel operator expects to enter NA-ECA (dd-mm-yyyy) (hh:mm UTC) 20-10-2014 10:00		Date/time vessel operator expects to exit NA-ECA (dd-mm-yyyy) (hh:mm UTC) 29-10-2014	
Projected days vessel's main propulsion engines will be in operation within About 1 day.			
Sulphur content of fuel oil in use when entering and operating in the NA-ECA LSFO = 0.47% ; HSFO = 2.91%			
Provide a description of actions taken to attempt to achieve compliance prior to entering NA-ECA, including a description of all attempts that were made to locate alternative sources of compliant fuel oil, and a description of the reason why compliant fuel oil was not available As per Charterers LSFO was not available at Last port of Call in China (Yangzhou). Thereafter Charterers contacted Aegean Marine Petroleum SA but was refused LSFO due to non availability. Then charterers contacted Marine Petrobulk but was refused LSFO due to non availability. Charterers also tried to get LSMGO at Prince Rupert but it does not meet the DMA specs. due to low flash point and high sulphur content.			
Name of suppliers contacted	Address		Date of contact (dd-mm-yyyy)
Marine Petrobulk	10 Pemberton Avenue, North Vancouver, Canada		07-10-2014
Aegean Bunkering	299 Park Avenue, 2nd Floor, New York NY 10171, USA		07-10-2014
In case of fuel oil supply disruption only			
Name of port at which vessel was scheduled to receive compliant fuel oil N.A.			
Name of the fuel oil supplier that was scheduled to deliver (and now reporting the non-availability) N.A.			

Operational constraints, if applicable

Describe any operation constraints that prevented using available compliant fuel oil (e.g. with respect to viscosity or other fuel oil parameters)

N.A.

Specify steps you have taken, or are taking, to resolve these operational constraints that will allow you to use all commercially available residual fuel oil blends

N.A.

Describe availability of compliant fuel oil at the first port-of-call in Canada, and plans to obtain it

Fuel is not available at first port of call in Canada (Prince Rupert) as per information received from Charterers.

If compliant fuel oil is not available at the first port-of-call in Canada, list the lowest sulphur content of available fuel oil(s) or the lowest sulphur content of available fuel oil at the next port-of-call in Canada

Vessel intend to go to Vancouver to bunker for compliant fuel.

If vessel or owner/operator has submitted a Fuel Oil Non-Availability Report to Canada in the previous 12 months, list the number of Fuel Oil Non-Availability Reports previously submitted and provide details on the dates and ports visited while using non-compliant fuel oil as set out below.

Report	Date (dd-mm-yyyy)	Port	Type of fuel	Comments
No.1	05-07-2014	Not fixed	IFO 380	Initial Report
No.2	07-07-2014	Prince Rupert	IFO 380	Permission granted by TC
No.3	14-07-2014	Vancouver Anchor	IFO 380	For receiving LSFO

Master name

Capt. Ajit Karpate

Vessel operator name

Fleet Management Ltd.

Local agent in Canada

Pacific Northwest Ship & cargo Services Inc.

Vessel owner name

Zeyno Maritime Ltd.

Name of designated corporate official

Capt. M. Sathya

Address (street, city, country, postal/zip code)

11/F Dah Singh Financial Centre; 108 Gloucester Road; Wanchai, Hong Kong

Telephone number

+85222988481



Capt. Ajit Karpate

Print name

17-10-2014

Date (dd-mm-yyyy)